Report on Countryside Access faults resolved within the Trawden Parish Council area in the 2023/2024 financial year

Referen	ce Path Nur	mber Location nam	ne Fault descrip	otion Ad	ction taken
97	65 15	9 Germany Far Raven Rock F	_	cult for larger re	the stile has been removed and eplaced with a Centrewire gate. A andrail on adjacent ditch crossing as been replaced.
98	85 11	0 Alderhurst Er	nd The steps or footpath are condition.		One damaged step was replaced nd topped up with stone.
99	04 17	2 Slackhead Fa	rm Broken gate	. G	Sate and gate post replaced.
100	29 16	1 Little Thorn E Farm	and hedge p		wo Centrewire gates installed in he gaps in the fence.
100	37 15	1 Germany Far	fence to kee	_	Centrewire gate installed.
100	53 23	9 Winewall to I Gap Farm	Bough Broken gate.		Sate replaced and hung on a new ost.
100	63 15	1 Little Laithe F	•	a kissing gate. ir	lew gate catch and spring nstalled to make gate self-closing nd secure.
100	69 17	6 Raven's Rock Wycoller	Fallen tree a footpath.		he tree has been removed by ontractor.
101	60 19	5 Fosters Leap	Broken kissii		he gate was replaced with a Centrewire gate.
1030	04 21	6 Wycoller Roa	ad Rotten gate	•	Old gate post removed and new ost installed and gate re-hung.
103	10 21	6 Wycoller Roa	d Gate difficul	•	ottom gate-eye replaced, gate djusted to operate easily.
103	25 22	5 Keighley Roa path to Wyco View			replacement gate was made and nstalled.
103	34 5	7 Lower Beard: Head	shaw Broken gate boundary wi Beardshaw F	th Middle g	Ve replaced the gate post and the ate and repaired the adjoining ence.
104	20	Snake Walk - Tracks	Tram Muddy and conditions.		Ve added some additional urfacing material to the footpath.
105	55 21	5 Wycoller Bec	ck Collapsed ga livestock to	_	Centrewire gate installed.

25 April 2024 Page 1 of 2

Reference	Path Number	Location name	Fault description	Action taken
10636	57	Lower Beardshaw Head	Fallen conifers blocking the footpath.	We cut back numerous small conifers which had fallen into the footpath.

25 April 2024 Page 2 of 2